

RECREATION GROUND COMMITTEE MEETING AGENDA

Tollesbury Parish Council

Notice is hereby given that the virtual Meeting of the **TOLLESBURY PARISH COUNCIL RECREATION GROUND COMMITTEE** will be held on Monday 3rd August 2020, via Zoom commencing at 6.30pm, to which members of the Recreation Ground Committee are summoned for the transaction of the under-mentioned business.

M. Curtis

Michelle Curtis - Clerk to the Council

28th July 2020

Councillors: T Lowther (Chairman), A St Joseph (Vice-Chairman), V Chambers, R Cole

THE PRESS AND PUBLIC ARE CORDIALLY INVITED TO ATTEND

Photographing, recording, broadcasting or transmitting the proceedings of a meeting by any means is permitted however the privacy of (i) persons who object to the same and (ii) children and vulnerable adults must be respected by anonymising the identities of such.

The meeting is virtual and is being held via Zoom. If you wish to attend the meeting, please contact the Clerk who will email you joining information.

1. Apologies for Absence

To receive apologies for absence.

2. Declaration of Interest

Members are reminded that they are required to declare any Disclosable Pecuniary Interests, Other Pecuniary Interests and Non-Pecuniary Interests which they know they might have in items of business on the agenda. They are reminded that they will need to repeat their declarations at the appropriate point in the meeting and leave the room if required under the Code of Conduct. Unforeseen interests must be declared similarly at the appropriate time.

3. Public Forum

Members of the public will be given an opportunity to put forward their question(s) or statement to the Council. The Chairman will at his discretion then decide if he is able to answer the question(s) or proposes to put the item on the agenda for the next meeting.



4. Minutes

To receive and approve the Minutes of the Recreation Ground Committe Meeting held on 21^{st} July 2020. #

5. Skate Park

To discuss quotations and options for the repair works/removal of the Skate Park. *

6. Tree survey

To discuss quotations for works to be carried out as per the recommendations from the Tree Survey Report. #

7. Annual Play Equipment Inspection

To receive the Annual Play Equipment Inspection Report and discuss repairs required to the equipment. *

8. Football

To discuss the pitch requirements for the 2020/21 season.

9. Recreation Ground Contract

To review the Litter Collection Contract for the Recreation Ground. *

10. Other Matters

To consider any other matters relating to the Recreation Ground.

Key: * = attached - # to follow

Clerk: Michelle Curtis

Address: 4 Valkyrie Close, Tollesbury, Essex CM9 8SL

Telephone: 01621 869039. Email: clerk@tollesburyparishcouncil.gov.uk



Woodrolfe Road, Tollesbury, Essex.

CM9 8SE

Telephone: 01621 869385-869440

Fax: 01621 868861

E:Mail: accounts@gamartengineering.co.uk Website: www.gamartengineering.co.uk

TO:

Tollesbury Parish Council

ATTN:

Michelle

DATE:

June 30, 2020

FROM:

Gary Frost

E-mail:-

tollesburypc@btinternet.com

N°. PAGES One

MESSAGE:

Ref: Skate Park, Recreation Ground

After thorough examination of the skate park we would advise as follows:-

We do not think that cutting out and re-plating holes would be very successful or a long term solution.

We would recommend, as we have done on the previous ramp, to re-plate all over, clean the welds flush and re-paint, also patch up the side where they have rusted through

@

£4,970.00/total

TERMS:

Nett Monthly Account CARRIAGE: Included in quotation

Please note: - Due to market instability and the occasional difficulty in obtaining steel we may not be able to guarantee specific delivery dates or hold quotations firm longer than seven days, from today's date.

The above quotation is subject to VAT at the rate prevailing at the time of invoicing.

We look forward to hearing from you in the near future.

Regards,

Gary Frost





Subject: Fwd: Tollesbury Skate Park

Date: Wednesday, 1 July 2020 at 11:00:17 British Summer Time

From: Michelle Curtis
To: Tollesbury PC

Sent from my iPhone

Begin forwarded message:

From: chaz hampson <chesmetalwork@hotmail.com>

Date: 19 June 2020 at 09:14:37 BST

To: Michelle Curtis <michellecurtisxx@icloud.com>

Subject: Re: Tollesbury Skate Park

Hi Michelle

Your skate park can be sorted without to much problem
I would replate where the holes are so it would be new steel in that area
Likewise the holes on the sides of the ramps would have new steel over them
Then everything would be repainted to suit surfaces and sides of ramps
The total cost for these works would be
£2500 complete job
Time wise it would be a full weeks work
I would not be able to start these works until the government allows hotels to reopen mid July

All the best Chaz

Get Outlook for iOS



the play inspection company

Annual Inspection

Maldon District Council

Tollesbury - Victorian Recreation Ground

Elysian Gardens, Tollesbury, Maldon, Essex,











Unit 5, Glenmore Business Park, Blackhill Road, Poole, Dorset, BH16 6NL t- 01202 590675 e- info@playinspections.co.uk





RPII Inspection Methodology

This document outlines the RPII position on inspections undertaken by the Inspectors listed on the RPII Register of Inspectors for Indoor Annual, Outdoor Operational and Outdoor Routine.

Inspections are undertaken with reference to the standards listed in this preamble only; where no date for the standard is given it the date of the standard will be that current at the time of inspection with the exception of where overlap periods are granted by the standards committee when standards are updated. The information contained in reports is provided to assist the owner/operator in fulfilling their responsibilities as detailed in the relevant standard. Other standards referenced within the listed standards do not form part of the inspection.

The following standards are relevant to all installations of equipment that are publicly accessible to users; this would include public parks, pay and play parks, schools, nurseries, public houses, holiday parks, indoor play centres, farm parks etc. All equipment used or employed in publicly accessible areas should meet with the requirements of the relevant standards (listed below);

BS EN 1176 Parts 1, 2, 3, 4, 5, 6, 10 & 11 Playground equipment intended for permanent installation outdoors & indoors.

BS EN 1176 Part 7 - 'Guidance on Installation, Inspection, Maintenance and Operation' (this document gives guidance to the owners/operators of the facility on the installation, inspection, maintenance and operation of playground equipment, including ancillary items).

Domestic play equipment falls outside of the scope of BS EN 1176 and has its own standard (BS EN 71 – Safety of Toys). Where domestic equipment can be identified this will be acknowledged in the report but any comments concerning compliance within the inspection will still refer to BS EN 1176.

Other equipment that is not clearly identified as unsupervised or domestic (natural play, self-build equipment etc.) will be assessed for compliance with the relevant standard listed below:

BS EN 15312 - Free access multi-sports equipment

BS EN 14974 - Skateparks

BS EN 16630 - Permanently installed outdoor fitness equipment

BS EN 16899 - Parkour equipment (plus RPII/API guidance notes)

Annual and Post Installation inspections will take into consideration compliance with current standards and defects related to wear and vandalism. Items not listed in the report have not been included in the inspection. The inspection will cover the playground equipment and the active area up to 3.0 metres around, or the fence line if closer.

Operational inspections only take into consideration defects related to wear and vandalism. Routine visual inspections (if undertaken) relate only to the most obvious defects such as broken or missing parts, vandalism and issues created by severe weather conditions (the intention is to identify hazards created by storm damage).

The inspection is non-dismantling, non-destructive and does not include for any structural, toxicology or impact assessments defined in the standard; however, the inspector will undertake a manual test for stability and if equipment fails under manual load, or any other hazard is identified as an unacceptable risk, the owner/operator will be notified as soon as practicably possible.

The inspector will access all standing surfaces as necessary on the equipment and assess all parts up to 2.5m above the standing surface. Where it is not possible to access parts of the equipment without employing an alternative means of access the report will record the action required by the owner/operator to ensure the continued safe use of the equipment. Ancillary equipment will be assessed using the inspector's knowledge and experience of the standards named in this document to ensure as far as is reasonably practicable the continued safe use of the items concerned. The owner/operator is responsible for the overall safety of the equipment and area. Inspectors who are trained to use ladders may use them where it is safe to do so, but if members of the public are present on-site ladders may not be used to access the equipment.

The inspector will not undertake any of the following works unless specifically agreed in writing at the time of order:

Checking the depth and underlying structural integrity of any surface areas and/or carrying out any testing of impact absorbing properties of any surfaces. The identification of any corrosion, rot or other deterioration in any apparatus or equipment other than by an external inspection or the inspection of any equipment (or part thereof) that is underground. Tightening any bolts, hinges or other fixing devices on any apparatus or equipment. Assessing or inspecting any electrical installations contained on any site and/or apparatus and/or equipment. Assessing or inspecting any water supplies and/or water features and/or any associated computerised systems (including carrying out any programming).

Where planting or trees are mentioned in the report no aboricultural or horticultural assessments of toxicity, suitability or condition are undertaken; the owner/operator should have suitable inspections provided by a competent person.

The owner/operator should have a 'design risk assessment' provided by the manufacturer/designer of the area for the equipment and location in which the facility is installed.

The operator is responsible for managing risks of their provision and is required by law to carry out a 'suitable and sufficient assessment' of the risks associated with a site or activity and this inspection shall be considered as contributing to the operator's discharge of this responsibility.

The details contained within the report are a snapshot of the condition at the time of inspection only and subsequent events may affect the condition of the facility. Suggested remedial actions are based on the knowledge and experience of the inspector and/ or that of the inspection company. The owner/operator should seek the advice of the manufacturer or a competent person at all times when undertaking repairs and/or modifications to equipment.

A full copy of the Play Inspection Company Ltd. Terms & Conditions is available on our website (www.playinspections.co.uk)

© The Play Inspection Company & the Register of Play Inspectors International January 2019





Table 1

The operator is responsible for following the guidance of the relevant standards. The standards give guidance on the installation, inspection, maintenance and operation of the various types of facilities. The inspection guidance is listed in Table 1, with an indication of which parts will be included in an RPII Annual or Post-Installation Inspection. The relevant standards also contain additional parts which the operator should follow.

| Inspection recommendations of relevant standards Refer to relevant standards for full text | Annual Main | RPII Annual Outdoor/ Fully enclosed Inspection |
|---|-------------|---|
| 6.1 and 6.2 c) Inspect and maintain in accordance with the manufacturer's instructions (see note 1) | ~ | X [1] |
| 6.2 a) Identify obvious hazards | ✓ | ✓ |
| 6.2 b) Check for operation, stability and wear (see note 2) | ~ | ✓ [2] |
| 6.2 b) Check sealed for life parts | ✓ | × |
| 6.2 b) Check for cleanliness, equipment ground clearances, ground surface finishes, exposed foundations, sharp edges, missing parts, excessive wear (of moving parts) and structural integrity (see note 2) | ~ | ✓ [2] |
| 6.2 c) Overall levels of safety of equipment | V | ✓ |
| 6.2 c) Overall levels of safety of foundations (see note 2) | ✓ | ✓ [2] |
| 6.2 c) Overall levels of safety of surfaces (see note 3) | ~ | ✓ [3] |
| 6.2 c) Compliance with the relevant parts of the standard (see note 4) | ~ | ✓ [4] |
| 6.2 c) Undertaking the responsibility of the operator's periodic, systematic assessment of the effectiveness of all their safety measures (BS EN 1176-7, 8.2.1) | ~ | X |
| 6.2 c) Effects of weather | ✓ | ✓ |
| 6.2 c) Presence of rot or corrosion (see note 2) | ~ | ✓ [2] |
| 6.2 c) Assessment of repairs made/added or replaced components (see note 5) | ~ | ✓ [5] |
| 6.2 c) Excavation/dismantling/additional measures | ✓ | × |
| 6.3.1 Assessment of glass reinforced plastics (see note 6) | ~ | ✓ [6] |
| 6.3.2 Maintenance of one post equipment (see note 2) | ~ | ✓ [2] |

NB The clause numbers in table 1 are taken from BS EN 1176-7. The content is equally applicable to all other relevant standards listed herein.

- [1] Playgrounds contain a range of equipment from different manufacturers and installed over a number of years; operators should implement any guidance provided by the manufacturer. Item specific detail is not readily available to RPII Playground Inspectors, whose report contributes to the operator's overall Annual Main Inspection as detailed in the relevant standards.
- [2] A manual test only is undertaken for stability. Wear and instability are only detectable where readily apparent without dismantling or destruction and without the use of tools, excavation or specialist equipment. Rot and corrosion are tested for with a hammer and/or steel rod. Decay in timber may exist which can only be found with specialist equipment.
- [3] Only the visible condition and dimensional compliance of surface extent is considered. Neither testing of impact attenuating properties nor measurement of the thickness of bound surfaces are undertaken on RPII annual inspections.
- [4] The inspection assesses compliance where this can be tested on site using manual methods without dismantling, destruction and without the use of tools or specialist equipment.
- [5] The operator should use manufacturer's recommended parts, or equivalent. We are unable to verify if such parts have been used, and any subsequent change in quality or performance.
- [6] Visible glass fibres will be noted in reports. The operator is responsible for repairs or replacement.

Risk Assessment Matrix

| | | | Scores in the report are multiplication factors of Likelihood x Severity | | | | | | | |
|------------|---|------------|--|---|---|---|--|--|--|--|
| | | | Severity>> | | | | | | | |
| Likelihood | Very High probability, if the situation is not addressed an accident is almost certain. | 5 | Very High | VL (5) | L (10) | M (15) | H (20) | VH (25) | | |
| | High probability an accident is probable without any added factor. | 4 | High | VL (4) | L (8) | M (12) | H (16) | H (20) | | |
| | Moderate probability an incident is foreseeable. | 3 | Moderate | VL (3) | L (6) | L (9) | M (12) | M (15) | | |
| | Some probability, requires a combination of factors to take place. | 2 | Low | VL (2) | VL (4) | L (6) | L (8) | L (10) | | |
| | No significant probability; lightning strike, freak accident. | 1 | Very Low | VL (1) | VL (2) | VL (3) | VL (4) | VL (5) | | |
| | | | | Very Low | Low | Moderate | High | Very High | | |
| | | | | 1 | 2 | 3 | 4 | 5 | | |
| | PI | | | No injury likely e.g. damaged or soiled clothing, minor bruising, grazes | Minor injury, laceration or bruising requiring first aid only | Injury requiring medical intervention e.g. cuts requiring stitches | Serious injury including concussions or fracture of long bones | Severe injury involving a potential life changing injury or fatality | | |
| | | Severity>> | | | | | | | | |

Note 1: The total risk scores included within our reports are a multipication factor of the calculated Likelihood and Severity of each finding. Both Likelihood and Severity are given a number between 1 - 5 as shown on the matrix above and these two numbers are then multiplied together to give the total risk score that is shown against defects on the report. Total risk scores can be divided in both directions, i.e. a total risk score of 12 could be a Likelihood (3) x Severity (4) or Likelihood (4) x Severity (3).

Note 2: When we inspect we only see a snapshot of the current condition of the equipment. It is the operators responsibility to ensure that there is a continuing level of maintenance to keep the equipment in good working order and the site fit for use.

Equipment has been assessed to the following standards where relevant:

BS EN 1176 Parts 1-11 (Playground equipment and surfacing)

BS EN 14974 (Facilities for users of roller sports equipment)

BS EN 15312 (Free access multi-sports equipment)

BS EN 16899 (Parkour Equipment)

BS EN 16630 (Outdoor Fitness Equipment).



Tollesbury - Victorian Recreation Ground

Inspection Ref: 1126525 Site Ref: 15139 Customer Order: N/A

Inspected: 17-June-2020 - 14:10 by Alan Lingley RPII Annual Inspector

Risk Assessment: 16 High Risk



Location:

The site is located in an area of public open space and is overlooked by a number of properties in the local community. **Disabled Access:**

Generally accessible; an area accessible to most.





6 - Low Risk

Item: Gate - Self Closing

Manufacturer:UnknownSurface Type:N/AItem Quantity:3Equipment Compliance:N/ASurface Area Compliance:N/A

Total Findings: 2



Finding 1

Gate locked at time of inspection due to Covid 19 - -

Finding 2

The surface has eroded in some areas - Reinstate the

surface



4 - Very Low Risk

Item: Gate - Maintenance

Manufacturer:UnknownSurface Type:N/AItem Quantity:1Equipment Compliance:N/ASurface Area Compliance:N/A

Total Findings: 1



Finding 1

This item is satisfactory - no work required -





4 - Very Low Risk

Fence - Bow Top Item:

Manufacturer: Unknown **Surface Type:** N/A **Item Quantity:** 1 **Equipment Compliance:** N/A Surface Area Compliance: N/A

Total Findings: 1



Finding 1

This item is satisfactory - no work required -



4 - Very Low Risk

Item: Sign

Manufacturer: Owner/Operator

Surface Type: N/A **Item Quantity:** 1 **Equipment Compliance:** N/A Surface Area Compliance: N/A


Total Findings: 1



Finding 1

This item is satisfactory - no work required -





Item: Bench

Manufacturer:Owner/OperatorSurface Type:Bonded Rubber Mulch

Item Quantity:2Equipment Compliance:N/ASurface Area Compliance:N/A

Total Findings: 1



Finding 1

There are weeds/vegetation growth between or around the edges of the surfacing - Remove weeds/vegetation growth

🌇 6 - Low Risk

Item:Picnic TableManufacturer:Owner/OperatorSurface Type:Bonded Rubber Mulch

Item Quantity:3Equipment Compliance:N/ASurface Area Compliance:N/A


Total Findings: 1



Finding 1

There are weeds/vegetation growth between or around the edges of the surfacing - Remove weeds/vegetation growth





Item:Litter BinManufacturer:Owner/Operator

Surface Type:N/AItem Quantity:1Equipment Compliance:N/ASurface Area Compliance:N/A

Total Findings: 1



Finding 1

The lid or door of the litter bin is not secured - Ensure the lid or door is kept locked

6 - Low Risk

Item:Site GeneralManufacturer:UnknownSurface Type:N/AItem Quantity:1Equipment Compliance:N/ASurface Area Compliance:N/A

Total Findings: 1



Finding 1

There is a loose mat in the area - Remove





6 - Low Risk

Item: Multi Play (Junior)
Manufacturer: Not Identified

Surface Type: Bonded Rubber Mulch

Item Quantity:1Equipment Compliance:NoSurface Area Compliance:Yes

Total Findings: 7



Finding 1

There are weeds/vegetation growth between or around the edges of the surfacing - Remove weeds/vegetation growth

Finding 2 There is an oper

There is an opening in the barriers exceeding the width allowed (500mm) in BS EN 1176, this is a low risk failure and no remedial action is required - Monitor - No remedial work recommended

Finding 3

A number of fixing(s) have worked loose - Secure all loose fixings

Finding 4

The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting - Treat any rusting components and repaint

Finding 5

A number of fixing(s) have worked loose on the wheel - Secure all loose fixings


Finding 6

The item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.2 head and neck entrapment in the barriers and/or steps - Monitor - No remedial work recommended

Finding 7

There are a number of dents in the slide surface - Monitor for any further deterioration and repair as required





Item: Climbing Frame

Manufacturer:Wicksteed PlaygroundsSurface Type:Grass Matrix Tiles

Item Quantity:1Equipment Compliance:NoSurface Area Compliance:Yes

Total Findings: 4



Finding 1

There are falls in excess of 600mm between adjacent components on the structure, in contravention of the recommendations set out in BS EN 1176 Part 1; 4.2.8.4 - Monitor - No remedial work recommended

Finding 3

The timber has a number of splits/shakes or air cracks and this may affect the stability or allow water ingress which will accelerate the rotting process - Monitor to ensure the splits do not cross through fixing points of the structure and/or cause any instability

Finding 2

The item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.2 head and neck entrapment in the barriers and/or steps - Monitor - No remedial work recommended

Finding 4

There is some strimmer / machinery damage apparent on the posts, this can penetrate the preservative applied to the timber and accelerate the rotting process - Monitor for any deterioration (rot) and replace as required



8 - Low Risk

Item:Free Standing SlideManufacturer:Wicksteed PlaygroundsSurface Type:Grass Matrix Tiles

Item Quantity:1Equipment Compliance:NoSurface Area Compliance:No

Total Findings: 8



Finding 1

There are a number of dents in the slide surface - Monitor for any further deterioration and repair as required

Finding 3 Finding 4

The item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.2 head and neck entrapment in the barriers and/or steps - Monitor - No remedial work recommended

Finding 5

A number of fixing(a) have worked lease. Secure all lease.

A number of fixing(s) have worked loose - Secure all loose fixings

ŭ

Finding 7
The bars rotate - Secure

Finding 2

There is an opening in the barriers exceeding the width

allowed (500mm) in BS EN 1176, and no guardrail has been provided; this is a low risk failure and no remedial action is required - Monitor - No remedial work recommended

There is some strimmer / machinery damage apparent on the posts, this can penetrate the preservative applied to the timber and accelerate the rotting process - Monitor for any deterioration (rot) and replace as required

Finding 6

There is/are finger entrapment/s in the slide starting section and the item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.6 Entrapment of fingers - Monitor - No remedial work recommended

Finding 8

The timber edging forms a hard object within the falling space of the equipment in contravention of the requirements of BS EN 1176 Part 1 - Monitor - No remedial work recommended





6 - Low Risk

Item:RoundaboutManufacturer:HuntsSurface Type:Wet Pour

Item Quantity:1Equipment Compliance:NoSurface Area Compliance:Yes

Total Findings: 2



Finding 1

There is/are finger entrapment/s in the seat and the item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.6 Entrapment of fingers - Monitor - No remedial work recommended

Finding 2

The underside of the rotating platform shall be smooth for the first 500mm towards the axis to comply with the requirements of BS EN 1176 Part 5 - Monitor - No remedial work recommended



6 - Low Risk

Item: Climbing Frame

Manufacturer:Wicksteed PlaygroundsSurface Type:Bonded Rubber Mulch

Item Quantity:1Equipment Compliance:YesSurface Area Compliance:Yes

Total Findings: 3



Finding 1

The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting - Treat any rusting components and repaint

Finding 2

The item has been damaged - Monitor for any further deterioration and replace as required

Finding 3

There are weeds/vegetation growth between or around the edges of the surfacing - Remove weeds/vegetation growth






6 - Low Risk

Item: Spring Cow
Manufacturer: Not Identified

Surface Type: Bonded Rubber Mulch

Item Quantity:1Equipment Compliance:YesSurface Area Compliance:Yes

Total Findings: 1



Finding 1

There are weeds/vegetation growth between or around the edges of the surfacing - Remove weeds/vegetation growth



6 - Low Risk

Item: Spring Bird Manufacturer: Not Identified

Surface Type: Bonded Rubber Mulch

Item Quantity:1Equipment Compliance:NoSurface Area Compliance:Yes

Total Findings: 3



Finding 1

The footrest peg is missing - Replace missing peg

Finding 2

The end of handgrips and/or footrests have a cross section of less than 15cm2 and fail to meet the requirements of BS EN 1176 Part 6 - Monitor - No remedial work recommended

Finding 3

There are weeds/vegetation growth between or around the edges of the surfacing - Remove weeds/vegetation growth





6 - Low Risk

1 Bay 2 Seat (Flat) Item: Wicksteed Playgrounds Manufacturer:

Wet Pour **Surface Type:**

Item Quantity: 1 **Equipment Compliance:** Nο Surface Area Compliance: Yes

Total Findings: 5



Finding 1

The seats are too close to the frame as defined in BS EN 1176 Part 2: this is a low risk failure and no remedial action is required - Monitor - No remedial work recommended

Finding 3

The chain openings are in excess of the 8.6mm as recommended by BS EN 1176 - Monitor - No remedial work edging surround or between the joints in the surfacing recommended

Finding 5

The bushes are showing signs of wear - Monitor for any further deterioration and replace as required

Finding 2

The paint is flaking off the metalwork - Rub down and re-

Finding 4

There are gaps opening between the surfacing and the Monitor for any further deterioration and repair as required



🥎 5 - Very Low Risk

Item: 1 Bay 2 Seat (Cradle)

Manufacturer: Not Identified Wet Pour **Surface Type:**

Item Quantity: Equipment Compliance: Surface Area Compliance: Yes


Total Findings: 1



Finding 1

The chain openings are in excess of the 8.6mm as recommended by BS EN 1176 - Monitor - No remedial work recommended





Item: Monkey Bars
Manufacturer: Not Identified

Surface Type:GrassItem Quantity:1Equipment Compliance:YesSurface Area Compliance:Yes

Total Findings: 3



Finding 1

The timber has a number of splits/shakes or air cracks and this may affect the stability or allow water ingress which will accelerate the rotting process - Monitor to ensure the splits do not cross through fixing points of the structure and/or cause any instability

Finding 3

There is some strimmer / machinery damage apparent on the posts, this can penetrate the preservative applied to the timber and accelerate the rotting process - Monitor for any deterioration (rot) and replace as required

Finding 2

The handgrips are becoming worn - Monitor for any further deterioration and replace as required





6 - Low Risk

Climbing Pole Item: Not Identified Manufacturer: Surface Type: **Grass Matrix Tiles**

Item Quantity: 1 **Equipment Compliance:** Yes Surface Area Compliance: Yes

Total Findings: 3



Finding 1

The fixings or components for this item were in excess of 2.5m above the standing surface and could not be fully accessed by the inspector. We have completed a visual inspection of the fixings from ground level but a maintenance inspection should be undertaken to assess the cause any instability condition, security and wear of the components at intervals in accordance with the manufacturers recommendations. -Inspect in accordance with the manufacturers recommendations

Finding 3

There is some strimmer / machinery damage apparent on the posts, this can penetrate the preservative applied to the timber and accelerate the rotting process - Monitor for any deterioration (rot) and replace as required

Finding 2

The timber has a number of splits/shakes or air cracks and this may affect the stability or allow water ingress which will accelerate the rotting process - Monitor to ensure the splits do not cross through fixing points of the structure and/or





6 - Low Risk

Item: Hurdles
Manufacturer: Not Identified

Surface Type:GrassItem Quantity:5Equipment Compliance:YesSurface Area Compliance:Yes

Total Findings: 3



Finding 1

The timber has a number of splits/shakes or air cracks and this may affect the stability or allow water ingress which will accelerate the rotting process - Monitor to ensure the splits do not cross through fixing points of the structure and/or cause any instability

Finding 3

There is some strimmer / machinery damage apparent on the posts, this can penetrate the preservative applied to the timber and accelerate the rotting process - Monitor for any deterioration (rot) and replace as required

Finding 2

The item has been damaged - Monitor for any further deterioration and replace as required

6 - Low Risk

Item: Parallel Bars
Manufacturer: Not Identified

Surface Type: Grass
Item Quantity: 1
Equipment Compliance: Yes
Surface Area Compliance: Yes

Total Findings: 2



Finding 1

The surface has eroded in some areas - Reinstate the surface

Finding 2

The timber has a number of splits/shakes or air cracks and this may affect the stability or allow water ingress which will accelerate the rotting process - Monitor to ensure the splits do not cross through fixing points of the structure and/or cause any instability





6 - Low Risk

Item:Sit Up StationManufacturer:Not Identified

Surface Type:GrassItem Quantity:1Equipment Compliance:YesSurface Area Compliance:Yes

Total Findings: 2



Finding 1

The timber has a number of splits/shakes or air cracks and this may affect the stability or allow water ingress which will accelerate the rotting process - Monitor to ensure the splits do not cross through fixing points of the structure and/or cause any instability

Finding 2

The item has been damaged - Monitor for any further deterioration and replace as required



6 - Low Risk

Item:Grind BoxManufacturer:Not IdentifiedSurface Type:Concrete

Item Quantity:1Equipment Compliance:YesSurface Area Compliance:Yes

Total Findings: 1



Finding 1

The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting - Treat any rusting components and repaint



Æ

12 - Moderate Risk

Item:Quarter PipeManufacturer:Not IdentifiedSurface Type:Concrete

Item Quantity:1Equipment Compliance:YesSurface Area Compliance:Yes

Total Findings: 1



Finding 1

Parts of the steel on this item have corroded excessively and the metal has perforated in places - Ensure all affected areas are treated and repaired

16 - High Risk

Item:Half PipeManufacturer:Not IdentifiedSurface Type:Concrete

Item Quantity:1Equipment Compliance:NoSurface Area Compliance:Yes

Total Findings: 3



Finding 1

The riding surface of the ramp is severely damaged- The damage on the surface of the ramps suggests that the metal riding surface is deteriorating we recommend an internal inspection of the item is carried to ascertain the structural stability of the item - Repair all damaged surfaces and carry out recommendations

Finding 3

Parts of the steel on this item have corroded excessively and the metal has perforated in places - Ensure all affected areas are treated and repaired

Finding 2

The height of the barrier is less than 1200mm and fails the requirements of BS EN 14974 - Monitor - No remedial work recommended





6 - Low Risk

Item:ShelterManufacturer:Not Identified

Surface Type: Grass Item Quantity: 1
Equipment Compliance: N/A
Surface Area Compliance: N/A

Total Findings: 2



Finding 1

The surface has eroded in some areas - Reinstate the

surface

Finding 2

The item is slightly loose in its foundations - Monitor for any further deterioration and repair as required



6 - Low Risk

Item: Multi Play (Toddler)
Manufacturer: Not Identified

Surface Type: Bonded Rubber Mulch

Item Quantity:1Equipment Compliance:YesSurface Area Compliance:Yes

Total Findings: 1



Finding 1

There are weeds/vegetation growth between or around the edges of the surfacing - Remove weeds/vegetation growth





6 - Low Risk

Free Standing Slide Item: Manufacturer: Not Identified

Surface Type: Bonded Rubber Mulch

Item Quantity: 1 **Equipment Compliance:** Yes Surface Area Compliance: Yes

Total Findings: 1



Finding 1

There are weeds/vegetation growth between or around the edges of the surfacing - Remove weeds/vegetation growth



1 4 - Very Low Risk

Item: See Saw Manufacturer: Quali-Cite Mixed Surface **Surface Type:**

Item Quantity: 1 **Equipment Compliance:** Yes Surface Area Compliance: Yes

Total Findings: 1



Finding 1

This item is satisfactory - no work required -





4 - Very Low Risk

Item: Wobble Board Manufacturer: Not Identified **Surface Type:** Mixed Surface

Item Quantity: 1 **Equipment Compliance:** Yes Surface Area Compliance: Yes

Total Findings: 1



Finding 1

This item is satisfactory - no work required -




8 - Low Risk

Item: Cable Runway Not Identified Manufacturer: **Surface Type:** Wet Pour

Item Quantity: 1 **Equipment Compliance:** No Surface Area Compliance: Yes

7 **Total Findings:**



Finding 1

The surface has eroded in some areas - Reinstate the

surface

Finding 2

The seat is less than 2.0 metres from the post when extended at 45 degrees at the end of the area of travel and does not meet the requirements of BS EN 1176 Part 4 -Adjust the cable stop position to ensure the minimum distance is maintained

Finding 3

any further deterioration and replace as required

Finding 4

The seat suspension cover has been damaged - Monitor for The height of the seat is less than 350mm when loaded and does not meet the requirements of BS EN 1176 Part 4 -Ensure the seat is a minimum of 350mm above ground level when loaded with 69.5kg

Finding 5

The surfacing around the item is damaged - Repair the damaged areas of surfacing

Finding 6

There are three turns of the cable on the drum - Refer to the contractor for confirmation of correct installation


Finding 7

There is the potential for users to pass through the freespace of the cableway when entering or exiting the play area - Monitor use





Findings information



Item: Ancillary Items - Gate - Self Closing Risk Level: N - Risk Assessment not Undertaken

Manufacturer: Unknown Surface: N/





Finding: Gate locked at time of inspection due to Covid 19 Action: -

6 - Low Risk (Finding 2)

 Item:
 Ancillary Items - Gate - Self Closing
 Risk Level:
 L - Low Risk

Manufacturer: Unknown Surface: N/A





Finding: The surface has eroded in some areas Action: Reinstate the surface







Item: Ancillary Items - Bench Risk Level: L - Low Risk

Manufacturer: Owner/Operator Surface: Bonded Rubber Mulch





Finding: There are weeds/vegetation growth between or around the edges of the surfacing

Action: Remove weeds/vegetation growth

6 - Low Risk (Finding 1)

Item: Ancillary Items - Picnic Table Risk Level: L - Low Risk

Manufacturer: Owner/Operator Surface: Bonded Rubber Mulch





Finding: There are weeds/vegetation growth between or around the edges of the surfacing

Action: Remove weeds/vegetation growth








Item: Ancillary Items - Litter Bin

Manufacturer: Owner/Operator

Risk Level: L - Low Risk Surface: N/A







Action: Ensure the lid or door is kept locked

6 - Low Risk (Finding 1)

Item: Ancillary Items - Site General

Manufacturer: Unknown

Risk Level: L - Low Risk Surface: N/A







Action: Remove







6 - Low Risk (Finding 1)

Item: Activity Equipment - Multi Play (Junior) Risk Level: L - Low Risk

Manufacturer: Not Identified Surface: Bonded Rubber Mulch





Finding: There are weeds/vegetation growth between or around the edges of the surfacing

Action: Remove weeds/vegetation growth

A

4 - Very Low Risk (Finding 2)

Item:Activity Equipment - Multi Play (Junior)Risk Level:V - Very Low RiskManufacturer:Not IdentifiedSurface:Bonded Rubber Mulch





Finding: There is an opening in the barriers exceeding the width allowed (500mm) in BS EN 1176, this is a low risk failure and no remedial action is required

Finding: There is an opening in the barriers exceeding the Action: Monitor - No remedial work recommended







Item: Activity Equipment - Multi Play (Junior) Risk Level: L - Low Risk

Manufacturer: Not Identified Surface: Bonded Rubber Mulch







Finding: A number of fixing(s) have worked loose

Action: Secure all loose fixings








Activity Equipment - Multi Play (Junior) Item:

Manufacturer: Not Identified









Finding: The paintwork on this item has been damaged or Action: Treat any rusting components and repaint worn exposing the metal underneath which is rusting





6 - Low Risk (Finding 5)

Activity Equipment - Multi Play (Junior) Risk Level: L - Low Risk Item:

Not Identified Surface: **Bonded Rubber Mulch** Manufacturer:



Finding: A number of fixing(s) have worked loose on the wheel



Action: Secure all loose fixings

5 - Very Low Risk (Finding 6)

Item: Activity Equipment - Multi Play (Junior) Risk Level: V - Very Low Risk Bonded Rubber Mulch Manufacturer: Not Identified Surface:



Finding: The item fails to meet the requirements of BS EN Action: Monitor - No remedial work recommended 1176 Part 1 4.2.7.2 head and neck entrapment in the barriers and/or steps










4 - Very Low Risk (Finding 7)

Item: Activity Equipment - Multi Play (Junior)

Manufacturer: Not Identified





Risk Level: V - Very Low Risk
Surface: Bonded Rubber Mulch



Action: Monitor for any further deterioration and repair as required

8 - Low Risk (Finding 1)

Item: Activity Equipment - Climbing Frame

Manufacturer: Wicksteed Playgrounds



Finding: There are falls in excess of 600mm between adjacent components on the structure, in contravention of the recommendations set out in BS EN 1176 Part 1; 4.2.8.4

Risk Level: L - Low Risk
Surface: Grass Matrix Tiles



Action: Monitor - No remedial work recommended





5 - Very Low Risk (Finding 2)

Activity Equipment - Climbing Frame Item: Risk Level: Wicksteed Playgrounds Manufacturer: Surface:



V - Very Low Risk

Finding: The item fails to meet the requirements of BS EN Action: Monitor - No remedial work recommended 1176 Part 1 4.2.7.2 head and neck entrapment in the barriers and/or steps

6 - Low Risk (Finding 3)

Activity Equipment - Climbing Frame Risk Level: L - Low Risk Item: Manufacturer: Wicksteed Playgrounds Surface: **Grass Matrix Tiles**





Finding: The timber has a number of splits/shakes or air Action: Monitor to ensure the splits do not cross through cracks and this may affect the stability or allow water ingress fixing points of the structure and/or cause any instability which will accelerate the rotting process







6 - Low Risk (Finding 4)

Item: Activity Equipment - Climbing Frame

Manufacturer: Wicksteed Playgrounds

Finding: There is some strimmer / machinery damage apparent on the posts, this can penetrate the preservative applied to the timber and accelerate the rotting process

Risk Level: L - Low Risk
Surface: Grass Matrix Tiles



Action: Monitor for any deterioration (rot) and replace as required

A

4 - Very Low Risk (Finding 1)

Item:Other - Free Standing SlideRisk Level:V - Very Low RiskManufacturer:Wicksteed PlaygroundsSurface:Grass Matrix Tiles



Finding: There are a number of dents in the slide surface



Action: Monitor for any further deterioration and repair as required



The Play Inspection Company Ltd Unit 5 Glenmore Business Park Blackhill Road Poole Dorset BH16 6NL 01202 590675

4 - Very Low Risk (Finding 2)

V - Very Low Risk Other - Free Standing Slide Risk Level: Item: Grass Matrix Tiles Manufacturer: Wicksteed Playgrounds Surface:





Finding: There is an opening in the barriers exceeding the width allowed (500mm) in BS EN 1176, and no guardrail has been provided; this is a low risk failure and no remedial action is required



The Play Inspection Company Ltd Unit 5 Glenmore Business Park Blackhill Road Poole Dorset BH16 6NL 01202 590675

5 - Very Low Risk (Finding 3)

Other - Free Standing Slide Item: Manufacturer: Wicksteed Playgrounds

V - Very Low Risk Risk Level: Surface: **Grass Matrix Tiles**







Finding: The item fails to meet the requirements of BS EN **Action:** Monitor - No remedial work recommended 1176 Part 1 4.2.7.2 head and neck entrapment in the barriers and/or steps







6 - Low Risk (Finding 4)

Item: Other - Free Standing Slide

Manufacturer: Wicksteed Playgrounds



Finding: There is some strimmer / machinery damage apparent on the posts, this can penetrate the preservative applied to the timber and accelerate the rotting process

Risk Level: L - Low Risk
Surface: Grass Matrix Tiles




Action: Monitor for any deterioration (rot) and replace as required

6 - Low Risk (Finding 5)

Item:Other - Free Standing SlideRisk Level:L - Low RiskManufacturer:Wicksteed PlaygroundsSurface:Grass Matrix Tiles



Finding: A number of fixing(s) have worked loose



Action: Secure all loose fixings







5 - Very Low Risk (Finding 6)

Item:Other - Free Standing SlideRisk Level:V - Very Low RiskManufacturer:Wicksteed PlaygroundsSurface:Grass Matrix Tiles



Finding: There is/are finger entrapment/s in the slide starting section and the item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.6 Entrapment of fingers



Action: Monitor - No remedial work recommended

T

6 - Low Risk (Finding 7)

Item:Other - Free Standing SlideRisk Level:L - Low RiskManufacturer:Wicksteed PlaygroundsSurface:Grass Matrix Tiles



Finding: The bars rotate



Action: Secure







8 - Low Risk (Finding 8)

Item: Other - Free Standing Slide

Manufacturer: Wicksteed Playgrounds

Risk Level: L - Low Risk
Surface: Grass Matrix Tiles



Finding: The timber edging forms a hard object within the falling space of the equipment in contravention of the requirements of BS EN 1176 Part 1



Action: Monitor - No remedial work recommended

A

5 - Very Low Risk (Finding 1)

Item: Rotor Play - Roundabout

Manufacturer: Hunts

Risk Level: V - Very Low Risk
Surface: Wet Pour



Finding: There is/are finger entrapment/s in the seat and the item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.6 Entrapment of fingers



Action: Monitor - No remedial work recommended







6 - Low Risk (Finding 2)

Item:Rotor Play - RoundaboutRisk Level:L - Low RiskManufacturer:HuntsSurface:Wet Pour





Finding: The underside of the rotating platform shall be smooth for the first 500mm towards the axis to comply with the requirements of BS EN 1176 Part 5

Action: Monitor - No remedial work recommended

6 - Low Risk (Finding 1)

Item: Activity Equipment - Climbing Frame Risk Level: L - Low Risk

Manufacturer: Wicksteed Playgrounds Surface: Bonded Rubber Mulch





Finding: The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting

Action: Treat any rusting components and repaint















Item: Rocking Equipment - Spring Cow Risk Level: L - Low Risk

Manufacturer: Not Identified Surface: Bonded Rubber Mulch



Finding: There are weeds/vegetation growth between or around the edges of the surfacing




Action: Remove weeds/vegetation growth

6 - Low Risk (Finding 1)

Item: Rocking Equipment - Spring Bird Risk Level: L - Low Risk

Manufacturer: Not Identified Surface: Bonded Rubber Mulch







Action: Replace missing peg







Item: Rocking Equipment - Spring Bird Risk Level: L - Low Risk

Manufacturer: Not Identified Surface: Bonded Rubber Mulch





Finding: The end of handgrips and/or footrests have a cross **Action:** Monitor - No remedial work recommended section of less than 15cm2 and fail to meet the requirements of BS EN 1176 Part 6

6 - Low Risk (Finding 3)

Item: Rocking Equipment - Spring Bird Risk Level: L - Low Risk

Manufacturer: Not Identified Surface: Bonded Rubber Mulch





Finding: There are weeds/vegetation growth between or around the edges of the surfacing

Action: Remove weeds/vegetation growth







4 - Very Low Risk (Finding 1)

V - Very Low Risk Swings - 1 Bay 2 Seat (Flat) Risk Level: Wicksteed Playgrounds Surface: Wet Pour Manufacturer:





Finding: The seats are too close to the frame as defined in Action: Monitor - No remedial work recommended BS EN 1176 Part 2; this is a low risk failure and no remedial action is required

6 - Low Risk (Finding 2)

Swings - 1 Bay 2 Seat (Flat) Risk Level: L - Low Risk Item: Wicksteed Playgrounds Surface: Wet Pour Manufacturer:







Finding: The paint is flaking off the metalwork

Action: Rub down and re-paint







5 - Very Low Risk (Finding 3)

tem: Swings - 1 Bay 2 Seat (Flat) Risk Level: V - Very Low Risk







Finding: The chain openings are in excess of the 8.6mm as **Action:** Monitor - No remedial work recommended recommended by BS EN 1176

6 - Low Risk (Finding 4)

Item:Swings - 1 Bay 2 Seat (Flat)Risk Level:L - Low RiskManufacturer:Wicksteed PlaygroundsSurface:Wet Pour





Finding: There are gaps opening between the surfacing and **Action:** Monitor for any further deterioration and repair as the edging surround or between the joints in the surfacing required







4 - Very Low Risk (Finding 5)

Item:Swings - 1 Bay 2 Seat (Flat)Risk Level:V - Very Low RiskManufacturer:Wicksteed PlaygroundsSurface:Wet Pour





Finding: The bushes are showing signs of wear

Action: Monitor for any further deterioration and replace as required

A

5 - Very Low Risk (Finding 1)

Item:Swings - 1 Bay 2 Seat (Cradle)Risk Level:V - Very Low RiskManufacturer:Not IdentifiedSurface:Wet Pour





Finding: The chain openings are in excess of the 8.6mm as **Action:** Monitor - No remedial work recommended recommended by BS EN 1176







6 - Low Risk (Finding 1)

Item:Activity Equipment - Monkey BarsRisk Level:L - Low RiskManufacturer:Not IdentifiedSurface:Grass





Finding: The timber has a number of splits/shakes or air Action: Monitor to ensure the splits do not cross through cracks and this may affect the stability or allow water ingress fixing points of the structure and/or cause any instability which will accelerate the rotting process

6 - Low Risk (Finding 2)

Item:Activity Equipment - Monkey BarsRisk Level:L - Low RiskManufacturer:Not IdentifiedSurface:Grass





Finding: The handgrips are becoming worn

Action: Monitor for any further deterioration and replace as required







Item:Activity Equipment - Monkey BarsRisk Level:L - Low RiskManufacturer:Not IdentifiedSurface:Grass



Finding: There is some strimmer / machinery damage apparent on the posts, this can penetrate the preservative applied to the timber and accelerate the rotting process



Action: Monitor for any deterioration (rot) and replace as required



The Play Inspection Company Ltd Unit 5 Glenmore Business Park Blackhill Road Poole Dorset BH16 6NL 01202 590675

(1)

0 - Risk Assessment not Undertaken (Finding 1)

Item: Activity Equipment - Climbing Pole

Manufacturer: Not Identified

Risk Level: Surface: N - Risk Assessment not Undertaken

Grass Matrix Tiles





Finding: The fixings or components for this item were in excess of 2.5m above the standing surface and could not be recommendations fully accessed by the inspector. We have completed a visual inspection of the fixings from ground level but a maintenance inspection should be undertaken to assess the condition, security and wear of the components at intervals in accordance with the manufacturers recommendations.

Action: Inspect in accordance with the manufacturers recommendations







6 - Low Risk (Finding 2)

Item:Activity Equipment - Climbing PoleRisk Level:L - Low RiskManufacturer:Not IdentifiedSurface:Grass Matrix Tiles






Finding: The timber has a number of splits/shakes or air Action: Monitor to ensure the splits do not cross through cracks and this may affect the stability or allow water ingress fixing points of the structure and/or cause any instability which will accelerate the rotting process

6 - Low Risk (Finding 3)

Item:Activity Equipment - Climbing PoleRisk Level:L - Low RiskManufacturer:Not IdentifiedSurface:Grass Matrix Tiles







Action: Monitor for any deterioration (rot) and replace as required







6 - Low Risk (Finding 1)

Outdoor Fitness Equipment - Hurdles Risk Level: L - Low Risk Item: Not Identified Surface: Manufacturer: Grass





Finding: The timber has a number of splits/shakes or air Action: Monitor to ensure the splits do not cross through cracks and this may affect the stability or allow water ingress fixing points of the structure and/or cause any instability which will accelerate the rotting process

6 - Low Risk (Finding 2)

Outdoor Fitness Equipment - Hurdles Risk Level: L - Low Risk Item: Not Identified Manufacturer:





Action: Monitor for any further deterioration and replace as required

Finding: The item has been damaged







6 - Low Risk (Finding 3)

Item:Outdoor Fitness Equipment - HurdlesRisk Level:L - Low RiskManufacturer:Not IdentifiedSurface:Grass



Finding: There is some strimmer / machinery damage apparent on the posts, this can penetrate the preservative applied to the timber and accelerate the rotting process



Action: Monitor for any deterioration (rot) and replace as required

6 - Low Risk (Finding 1)

Item:Activity Equipment - Parallel BarsRisk Level:L - Low RiskManufacturer:Not IdentifiedSurface:Grass



Finding: The surface has eroded in some areas



Action: Reinstate the surface







6 - Low Risk (Finding 2)

Item:Activity Equipment - Parallel BarsRisk Level:L - Low RiskManufacturer:Not IdentifiedSurface:Grass





Finding: The timber has a number of splits/shakes or air cracks and this may affect the stability or allow water ingress fixing points of the structure and/or cause any instability which will accelerate the rotting process

6 - Low Risk (Finding 1)

Item:Outdoor Fitness Equipment - Sit Up Station Risk Level:L - Low RiskManufacturer:Not IdentifiedSurface:Grass





Finding: The timber has a number of splits/shakes or air **Action:** Monitor to ensure the splits do not cross through cracks and this may affect the stability or allow water ingress fixing points of the structure and/or cause any instability which will accelerate the rotting process







6 - Low Risk (Finding 2)

Item:Outdoor Fitness Equipment - Sit Up Station Risk Level:L - Low RiskManufacturer:Not IdentifiedSurface:Grass





Finding: The item has been damaged

Action: Monitor for any further deterioration and replace as required

6 - Low Risk (Finding 1)

Item:Wheeled Sports - Grind BoxRisk Level:L - Low RiskManufacturer:Not IdentifiedSurface:Concrete





Finding: The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting

Finding: The paintwork on this item has been damaged or Action: Treat any rusting components and repaint







Item: Wheeled Sports - Quarter Pipe

Manufacturer: Not Identified



Finding: Parts of the steel on this item have corroded excessively and the metal has perforated in places


Risk Level: M - Moderate Risk
Surface: Concrete



Action: Ensure all affected areas are treated and repaired









Finding: The riding surface of the ramp is severely damaged- The damage on the surface of the ramps suggests that the metal riding surface is deteriorating we recommend an internal inspection of the item is carried to ascertain the structural stability of the item



Action: Repair all damaged surfaces and carry out recommendations







Item:Wheeled Sports - Half PipeRisk Level:L - Low RiskManufacturer:Not IdentifiedSurface:Concrete






Finding: The height of the barrier is less than 1200mm and **Action:** Monitor - No remedial work recommended fails the requirements of BS EN 14974








Item: Wheeled Sports - Half Pipe

Manufacturer: Not Identified











Finding: Parts of the steel on this item have corroded excessively and the metal has perforated in places

Action: Ensure all affected areas are treated and repaired









Risk Level: L - Low Risk Surface: Grass



Finding: The surface has eroded in some areas

Action: Reinstate the surface

6 - Low Risk (Finding 2)

Item: Ancillary Items - Shelter

Manufacturer: Not Identified

Risk Level: L - Low Risk Surface: Grass




Finding: The item is slightly loose in its foundations

Action: Monitor for any further deterioration and repair as required







Item: Activity Equipment - Multi Play (Toddler) Risk Level: L - Low Risk

Manufacturer: Not Identified Surface: Bonded Rubber Mulch





Finding: There are weeds/vegetation growth between or around the edges of the surfacing

Action: Remove weeds/vegetation growth

6 - Low Risk (Finding 1)

Item: Other - Free Standing Slide Risk Level: L - Low Risk

Manufacturer: Not Identified Surface: Bonded Rubber Mulch





Finding: There are weeds/vegetation growth between or around the edges of the surfacing

Action: Remove weeds/vegetation growth













Item:Other - Cable RunwayRisk Level:L - Low RiskManufacturer:Not IdentifiedSurface:Wet Pour






Finding: The seat is less than 2.0 metres from the post when extended at 45 degrees at the end of the area of travel minimum distance is maintained and does not meet the requirements of BS EN 1176 Part 4







Other - Cable Runway Risk Level: L - Low Risk Item: Manufacturer: Not Identified Surface: Wet Pour



Finding: The seat suspension cover has been damaged



Action: Monitor for any further deterioration and replace as required

8 - Low Risk (Finding 4)

Item: Other - Cable Runway Risk Level: L - Low Risk Manufacturer: Not Identified Surface: Wet Pour



Finding: The height of the seat is less than 350mm when loaded and does not meet the requirements of BS EN 1176 ground level when loaded with 69.5kg Part 4



Action: Ensure the seat is a minimum of 350mm above







Item:Other - Cable RunwayRisManufacturer:Not IdentifiedSu

Risk Level: L - Low Risk Surface: Wet Pour








Finding: The surfacing around the item is damaged

Action: Repair the damaged areas of surfacing







Item: Other - Cable Runway Risk Level: N - Risk Assessment not Undertaken

Manufacturer: Not Identified Surface: Wet Pour



Finding: There are three turns of the cable on the drum

Action: Refer to the contractor for confirmation of correct installation

8 - Low Risk (Finding 7)

Item:Other - Cable RunwayRisk Level:L - Low RiskManufacturer:Not IdentifiedSurface:Wet Pour



Finding: There is the potential for users to pass through the **Action:** Monitor use freespace of the cableway when entering or exiting the play

area



TOLLESBURY PARISH COUNCIL



www.essexinfo.net/tollesbury-parish-council

GROUNDS MAINTENANCE CONTRACTS

LITTER COLLECTION AND SWEEP CONTRACT PERIOD –

Bus Shelter

- Sweep bus shelter daily.
- 2. Keep the bus shelter free from weeds
- 3. Sweep gutter around bus shelter daily
- 4. Disinfect under and around bench

Recreation Ground

- To collect litter and glass from the grounds of the Recreation Ground, Car Park and Children's Play Area every other day. (Monday, Wednesday, Friday and Sunday Morning)
- 2. To collect litter and glass from the perimeter of the Recreation Ground.
- 3. To carry out a visual inspection of all items of play equipment as listed below once a month:

a) Junior Swing

b) Toddler Swing

c) Multi-play C/W slide

d) Wooden Climber Platform

e) Tower and Slide

f) Seesaw

g) Igloo climber

h) Roundabout

i) Aerial Runway

j) Exercise Trail

k) Overhead Ladders

I) Vertical Bars

m) Playship

n) Springers

o) Skate Park

p) Youth Shelter

- 4. To carry out a visual inspection of all benches, dog and litter bins once a month
- 5. To carry out an inspection of the football goal posts once a month ensuring that all nuts/bolts are tight and secure.
- 6. To check the drain in the car park and ensure it is clean and clear of leaves once a month.
- To complete an Inspection Report indicating any items which require further attention by the Parish Council (e.g. tightening, replacing, oiling).
 All completed Inspection Reports should be submitted to the Council on a monthly basis with the invoice.

Clerk: Michelle Curtis, 4 Valkyrie Close, Tollesbury, Maldon, Essex CM9 8SL Tel: 01621 869039 e-mail: tollesburypc@btinternet.com

APPLICABLE TO ALL CONTRACTS

Contractor(s) should be aware of all Health and Safety legislation and should always work within the legislation and in a safe and suitable manner.

Contractor(s) should provide all necessary tools in order to perform the above duties.

Contractor(s) must provide and ensure that adequate liability insurance is in place, and provide details of this cover to the Parish Council.

Clerk: Michelle Curtis, 4 Valkyrie Close, Tollesbury, Maldon, Essex CM9 8SL Tel: 01621 869039 e-mail: tollesburypc@btinternet.com